

# ERITYISTÄ HUOLTA AIHEUTTAVIEN AINEIDEN TURVALLISTA KÄYTTÖÄ KOSKEVAT TIEDOT

## REACH-ASETUKSEN ARTIKLAN 33 TIEDOT KOSKIEN ERITYISTÄ HUOLTA AIHEUTTAVIA AINEITA

Hyvä asiakas

REACH-asetuksen (asetus EY N:o 1907/2006) artiklan 33(1) tarkoituksena on, että toimitettujen tuotteiden asiakkaat voivat ryhtyä asianmukaisiin riskienhallintatoimenpiteisiin käyttäkseen turvallisesti tuotteita, joissa on tämänhetkiseen mahdollisesti sisällytettävien luvanvaraisten aineiden luetteloon sisältyviä erityistä huolta aiheuttavia aineita.

FORD tukee yleisesti REACH-asetuksen ja nimenomaisesti artiklan 33(1) taustalla olevia tavoitteita. Ne ovat linjassa oman sitoumuksemme kanssa, joka on edistää tuotteidemme vastuullista valmistusta, käsittelyä ja käyttöä.

### **Eryistä huolta aiheuttavien aineiden tunnistaminen**

Eryistä huolta aiheuttavat aineet, joiden massaprosentti on komponenttituotteissa suurempi kuin 0,1 %, on esitetty kyseisen ajoneuvon/osan erityistä huolta aiheuttavien aineiden luettelossa toimitusketjultamme saatujen tietojen ja omien tuotetietojemme perusteella.

### **Eryistä huolta aiheuttavia aineita sisältävien tuotteiden erityiset turvallista käyttöä koskevat tiedot**

Eryistä huolta aiheuttavia aineita sisältävien tuotteiden erityiset turvallista käyttöä koskevat tiedot lisätään soveltuvien osien kyseisen ajoneuvon/osan asianmukaiseen erityistä huolta aiheuttavien aineiden luetteloon.

### **Tuotteiden yleiset turvallista käyttöä koskevat tiedot**

Jokaisen FORD-ajoneuvon mukana toimitetaan omistajan käsikirja, jossa on turvallista käyttöä koskevat tiedot ajoneuvon omistajalle/käyttäjälle. FORDin tiedot koskien ajoneuvojen korjausta ja huoltoa sekä alkuperäisiä osia sisältävät myös turvallista käyttöä koskevat tiedot huoltohenkilöstölle.

Mikäli kyseisen ajoneuvon/osan erityistä huolta aiheuttavien aineiden luettelossa olevia erityistä huolta aiheuttavia aineita on tämän ajoneuvon osissa, ne on sisällytetty siten, että mahdollinen asiakkaiden altistuminen on mahdollisimman pieni ja ihmisille ja ympäristölle ei aiheudu vaaraa. Tämä edellyttää, että ajoneuvoa

ja sen osia käytetään tarkoituksenmukaisesti ja että mahdolliset korjaus-, huolto- ja kunnossapitotyöt suoritetaan niitä koskevien teknisten ohjeiden ja alan vakiintuneiden hyvien käytäntöjen mukaisesti.

Romuajoneuvo voidaan hävittää Euroopan unionissa laillisesti vain valtuutetussa esikäsittelylaitoksessa. Ajoneuvon osat tulee hävittää paikallisesti sovellettavien lakien ja paikallisten viranomais määräysten mukaisesti.

## Malli: Ford Transit Connect / Tourneo Connect

**Erityistä huolta aiheuttavien aineiden luettelo perustuu Euroopan kemikaaliviraston mahdollisesti sisällytettävien aineiden luetteloon (1.7.2017).**

**Erityistä huolta aiheuttavia aineita sisältävien tuotteiden erityiset turvallista käyttöä koskevat tiedot**

Erityisiä turvallista käyttöä koskevia tietoja ei tarvita – noudata tuotteiden yleisiä turvallista käyttöä koskevia tietoja.

Commodity	REACH SVHC
A/C Compressor	4,4'-Isopropylidenediphenol [80-05-7] Diboron-trioxide [1303-86-2] Lead-monoxide [1317-36-8]
Accessories	1,2-Dimethoxyethane [110-71-4] 4,4'-Isopropylidenediphenol [80-05-7] C,C'-azodi(formamide) [123-77-3]
Adaptive Cruise Control	Boric acid [10043-35-3] Diboron-trioxide [1303-86-2]
AIS - Air Cleaner and Low Pressure Ducts	Lead(II,IV)-oxide [1314-41-6] Lead-monoxide [1317-36-8]
Antenna	Diboron-trioxide [1303-86-2]
Audio and Navigation Head Units	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9] Diboron-trioxide [1303-86-2] Lead titanium zirconium oxide [12626-81-2] Lead-monoxide [1317-36-8] Lead-titanium-trioxide [12060-00-3]
Body Structure - Dash and Cowl	C,C'-azodi(formamide) [123-77-3]
Body Structure - Decklid/Liftgate (incl Hinge/Supt)	Nonoxinol [9016-45-9]

Body Structure - Floor Pan - Front Floor and Side Sill	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Diboron-trioxide [1303-86-2]
	Refractory ceramic fibres [142844-00-6]
Bodyside, Wheel Arch, Rocker Moldings	Nonoxinol [9016-45-9]
Brake - Parking	2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Brake Actuation	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Cooling Fans	4,4'-Isopropylidenediphenol [80-05-7]
EDS Wiring Assembly & Components	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Boric acid [10043-35-3]
	Diboron-trioxide [1303-86-2]
	Hexahydromethylphthalic-anhydride [25550-51-0]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
	Lead-titanium-trioxide [12060-00-3]
	Nonoxinol [9016-45-9]
Electro/Mechanical Devices	Diboron-trioxide [1303-86-2]
Electro/Mechanical Devices - Security	Lead(II,IV)-oxide [1314-41-6]
Electronic Control Panel and CCH	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
Electronic Modules - Displays	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Boric acid [10043-35-3]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Electronic Modules - Headlamp	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
Electronic Modules - SYNC	4,4'-Isopropylidenediphenol [80-05-7]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
	Lead-titanium-trioxide [12060-00-3]
Engine Covers and Badges	Diboron-trioxide [1303-86-2]
Evaporator and Blower Assembly (HVAC Module)	2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
	4,4'-Isopropylidenediphenol [80-05-7]
	Boric acid [10043-35-3]
	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
	Imidazolidine-2-thione [96-45-7]
	Lead-monoxide [1317-36-8]
	Lead-titanium-trioxide [12060-00-3]
	Nonoxinol [9016-45-9]
	Refractory ceramic fibres [142844-00-6]

Exhaust Hot End (Catalytic Converter)	Refractory ceramic fibres [142844-00-6]
Fixed Glass	Diboron-trioxide [1303-86-2]
Fixed Glass Roof	Diboron-trioxide [1303-86-2]
Fuel Filler Pipes	Imidazolidine-2-thione [96-45-7]
Fuel Injection	Imidazolidine-2-thione [96-45-7]
	Lead-monoxide [1317-36-8]
Fuel Lines	2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Glass And Channel Assy - Front/Rear	Diboron-trioxide [1303-86-2]
Half Shaft(s)	Sodium borate, decahydrate [1303-96-4]
Headlamp / Side Marker	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Heat Shields - Engine Bay/Underfloor	Diboron-trioxide [1303-86-2]
Instrument Cluster	Boric acid [10043-35-3]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Interior Lighting	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
IP Finish Panels/Registers	2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
	Boric acid [10043-35-3]
Latches - Hood, Decklid and Liftgate Latches	Imidazolidine-2-thione [96-45-7]
	Nonoxinol [9016-45-9]
Latches - Side Door/Latch Mini Module	Nonoxinol [9016-45-9]
Locks	1,2-Dimethoxyethane [110-71-4]
	Diboron-trioxide [1303-86-2]
	Hexahydromethylphthalic-anhydride [25550-51-0]
	Lead-monoxide [1317-36-8]
Luggage and Interior Cargo Management/Covers	Imidazolidine-2-thione [96-45-7]
Mirrors	C,C'-azodi(formamide) [123-77-3]
Paint	Nonoxinol [9016-45-9]
PATS Transceiver	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
	Silicic acid, lead salt [11120-22-2]
PCV System	Imidazolidine-2-thione [96-45-7]
	Lead-titanium-trioxide [12060-00-3]
Powertrain Control Module (PCM/EEC/ ECM)	4,4'-Isopropylidenediphenol [80-05-7]
	Lead-monoxide [1317-36-8]
PT Sensors	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Seats - Foam - Cut and Sew	4,4'-Isopropylidenediphenol [80-05-7]

	Boric acid [10043-35-3]
	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Seats - JIT	C,C'-azodi(formamide) [123-77-3]
Seats - Structures	C,C'-azodi(formamide) [123-77-3]
Shifter Cables/Brackets - Auto	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
	N,N-Dimethylacetamide [127-19-5]
Side and Rear Vision (BLIS)	Lead-titanium-trioxide [12060-00-3]
Smart Junction Box & Body Control Module (SPDJB)	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
Speakers / Tweeters	Imidazolidine-2-thione [96-45-7]
Steering Column	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
Steering Gear and Linkage	Diboron-trioxide [1303-86-2]
Steering Wheel, Drive Air Bag	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Switches - General Use	Diboron-trioxide [1303-86-2]
Switches - Headlamp. Window & Door	4,4'-Isopropylidenediphenol [80-05-7]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
Taillamp / Redundant	Diboron-trioxide [1303-86-2]
Temperature Sensors - Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
Throttle Bodies	Diboron-trioxide [1303-86-2]
TMK and Tools	Imidazolidine-2-thione [96-45-7]
TPMS	1,2-Dimethoxyethane [110-71-4]
Transmission - Auto	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1]
Transmission - Manual	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1]
	Nonoxinol [9016-45-9]
Underbody Shields and Wheel Liners	Diboron-trioxide [1303-86-2]
Wiper Assembly (Rear, Front) & Washer System	Boric acid [10043-35-3]
	Diboron-trioxide [1303-86-2]
Appliques / Taillamp / Battery / Bumper / Speakers	C,C'-azodi(formamide) [123-77-3]
	Nonoxinol [9016-45-9]
(blank)	(blank)