

# ERITYISTÄ HUOLTA AIHEUTTAVIEN AINEIDEN TURVALLISTA KÄYTTÖÄ KOSKEVAT TIEDOT

## REACH-ASETUKSEN ARTIKLAN 33 TIEDOT KOSKIEN ERITYISTÄ HUOLTA AIHEUTTAVIA AINEITA

Hyvä asiakas

REACH-asetuksen (asetus EY N:o 1907/2006) artiklan 33(1) tarkoituksena on, että toimitettujen tuotteiden asiakkaat voivat ryhtyä asianmukaisiin riskienhallintatoimenpiteisiin käyttääkseen turvallisesti tuotteita, joissa on tämänhetkiseen mahdollisesti sisällytettävien luvanvaraisten aineiden luetteloon sisältyviä erityistä huolta aiheuttavia aineita.

FORD tukee yleisesti REACH-asetuksen ja nimenomaisesti artiklan 33(1) taustalla olevia tavoitteita. Ne ovat linjassa oman sitouksemme kanssa, joka on edistää tuotteidemme vastuullista valmistusta, käsittelyä ja käyttöä.

### **Eryistä huolta aiheuttavien aineiden tunnistaminen**

Eryistä huolta aiheuttavat aineet, joiden massaprosentti on komponenttituotteissa suurempi kuin 0,1 %, on esitetty kyseisen ajoneuvon/osan erityistä huolta aiheuttavien aineiden luettelossa toimitusketjultamme saatujen tietojen ja omien tuotetietojemme perusteella.

### **Eryistä huolta aiheuttavia aineita sisältävien tuotteiden erityiset turvallista käyttöä koskevat tiedot**

Eryistä huolta aiheuttavia aineita sisältävien tuotteiden erityiset turvallista käyttöä koskevat tiedot lisätään soveltuvin osin kyseisen ajoneuvon/osan asianmukaiseen erityistä huolta aiheuttavien aineiden luetteloon.

### **Tuotteiden yleiset turvallista käyttöä koskevat tiedot**

Jokaisen FORD-ajoneuvon mukana toimitetaan omistajan käsikirja, jossa on turvallista käyttöä koskevat tiedot ajoneuvon omistajalle/käyttäjälle. FORDin tiedot koskien ajoneuvojen korjausta ja huoltoa sekä alkuperäisiä osia sisältävät myös turvallista käyttöä koskevat tiedot huoltohenkilöstölle.

Mikäli kyseisen ajoneuvon/osan erityistä huolta aiheuttavien aineiden luettelossa olevia erityistä huolta aiheuttavia aineita on tämän ajoneuvon osissa, ne on sisällytetty siten, että mahdollinen asiakkaiden altistuminen on mahdollisimman pieni ja ihmisille ja ympäristölle ei aiheudu vaaraa. Tämä edellyttää, että ajoneuvoa ja sen osia käytetään tarkoituksenmukaisesti ja että mahdolliset korjaus-, huolto- ja kunnossapitotyöt suoritetaan niitä koskevien teknisten ohjeiden ja alan vakiintuneiden hyvien käytäntöjen mukaisesti.

Romuajoneuvo voidaan hävittää Euroopan unionissa laillisesti vain valtuutetussa esikäsittelylaitoksessa. Ajoneuvon osat tulee hävittää paikallisesti sovellettavien lakien ja paikallisten viranomais määräysten mukaisesti.

## Malli: Ford KA+

Erityistä huolta aiheuttavien aineiden luettelo perustuu Euroopan kemikaaliviraston mahdollisesti sisällytettävien aineiden luetteloon 1. heinäkuuta 2020

Erityistä huolta aiheuttavia aineita sisältävien tuotteiden erityiset turvallista käyttöä koskevat tiedot

Erityisiä turvallista käyttöä koskevia tietoja ei tarvita – noudata tuotteiden yleisiä turvallista käyttöä koskevia tietoja.

Commodity	REACH SVHCs
<b>A/C Compressor</b>	Lead7439-92-1
	Tris(nonylphenyl)phosphite26523-78-4
<b>A/C Lines, Receiver Drier and Accumulator</b>	Decamethylcyclopentasiloxane541-02-6
	Lead7439-92-1
<b>ABS/ESC Module</b>	Octamethylcyclotetrasiloxane556-67-2
	Lead7439-92-1
<b>Accessories</b>	Lead-monoxide1317-36-8
	1,2-Dimethoxyethane110-71-4
<b>AIS - High Pressure Ducts</b>	Lead7439-92-1
	Lead7439-92-1
<b>Alternator</b>	Decamethylcyclopentasiloxane541-02-6
	Lead7439-92-1
	Octamethylcyclotetrasiloxane556-67-2
<b>Antenna</b>	Lead7439-92-1
<b>Appliques (Pillar, Decklid, Roof)</b>	C,C'-azodi(formamide)123-77-3
<b>Audio and Navigation Head Units</b>	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
	Lead-titanium-trioxide12060-00-3
<b>Battery</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Body Moldings - Roof Rack</b>	C,C'-azodi(formamide)123-77-3
	Lead7439-92-1
<b>Body Structure - Floor Pan - Front Floor and Side Sill</b>	Boric acid10043-35-3
	Lead7439-92-1
<b>Brake Actuation</b>	C,C'-azodi(formamide)123-77-3
	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Brake Tubes and Hoses</b>	Lead7439-92-1

<b>Brakes - Caliper &amp; Anchor Brkt Assy (Front, Rear)</b>	Lead7439-92-1
<b>Brakes - Drum (Front/Rear)</b>	Lead7439-92-1
<b>Clutch / DMF (Dual Mass Flywheel)</b>	C,C'-azodi(formamide)123-77-3
	Lead7439-92-1
<b>Console Floor/Rear</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol25973-55-1
<b>Control Arm and Bushing Assembly</b>	Boric acid10043-35-3
	Cobalt-dichloride7646-79-9
<b>Cooling Hoses &amp; Bottles</b>	Lead7439-92-1
<b>Door Handles</b>	Lead7439-92-1
<b>Dressed Engines Module</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
	Octamethylcyclotetrasiloxane556-67-2
<b>EDS Wiring Assembly &amp; Components</b>	4,4'-Isopropylidenediphenol80-05-7
	Boric acid10043-35-3
	C,C'-azodi(formamide)123-77-3
	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>EGR System (Gas/Diesel)</b>	Lead7439-92-1
<b>Electronic Control Panel and CCH</b>	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione2451-62-9
	4,4'-Isopropylidenediphenol80-05-7
	Diboron-trioxide1303-86-2
	Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether9002-93-1
	Lead titanium zirconium oxide12626-81-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
	Octamethylcyclotetrasiloxane556-67-2
<b>Electronic Modules - Displays</b>	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Electronic Modules - SYNC</b>	2-Methylimidazole693-98-1
	Diboron-trioxide1303-86-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Engine Covers and Badges</b>	Lead7439-92-1
<b>Engine Sealing (Including head gaskets)</b>	Lead7439-92-1
<b>Evaporator and Blower Assemby (HVAC Module)</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
	Lead-titanium-trioxide12060-00-3
<b>Exhaust Hot End (Catalytic Convertor)</b>	Refractory ceramic fibres142844-00-6
<b>FEAD</b>	Lead7439-92-1
<b>Fuel Filler Pipes</b>	Imidazolidine-2-thione96-45-7
<b>Fuel Tanks</b>	Lead7439-92-1
<b>Glass And Channel Assy - Front/Rear</b>	Lead7439-92-1
<b>GOR and Radiator Support</b>	Lead7439-92-1
<b>Headliner / Sunvisor</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one71868-10-5

<b>Instrument Cluster</b>	Lead7439-92-1
<b>IP Finish Panels/Registers</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol25973-55-1
<b>Latches - Hood, Decklid and Liftgate Latches</b>	4,4'-Isopropylidenediphenol80-05-7
	Boric acid10043-35-3
	Imidazolidine-2-thione96-45-7
	Lead7439-92-1
<b>Latches - Side Door/Latch Mini Module</b>	Lead7439-92-1
<b>Locks</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Mirrors</b>	Lead7439-92-1
<b>PATS Transceiver</b>	Diboron-trioxide1303-86-2
	Lead titanium zirconium oxide12626-81-2
	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Pedal Box</b>	Di-(2-ethylhexyl)phthalat117-81-7
<b>Plastic Bumpers and Fascias</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Powertrain Control Module (PCM/EEC/ ECM)</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
	Lead-titanium-trioxide12060-00-3
<b>PT Mounts</b>	Lead7439-92-1
<b>PT Sensors</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Sealing - Glass Runs and Belt Moldings</b>	Phenol, dimethyl-, phosphate (3:1)25155-23-1
<b>Seat Belts (Front and Rear)</b>	Cobalt sulphate10124-43-3
<b>Seats - JIT</b>	Lead7439-92-1
<b>Shifter Cables/Brackets - Auto</b>	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene13560-89-9
	C,C'-azodi(formamide)123-77-3
	Dihexyl-phthalate84-75-3
	Lead7439-92-1
<b>Steering Column</b>	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Switches - General Use</b>	Lead7439-92-1
<b>Switches - Headlamp. Window &amp; Door</b>	4,4'-Isopropylidenediphenol80-05-7
	Lead7439-92-1
<b>Temperature Sensors - Climate</b>	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione2451-62-9
	Lead7439-92-1
<b>Tires</b>	Lead7439-92-1
<b>TPMS</b>	1,2-Dimethoxyethane110-71-4
	1,3-Propanesultone1120-71-4
	Lead7439-92-1
<b>Transmission - Auto</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one71868-10-5
	Lead7439-92-1
	Lead-monoxide1317-36-8
<b>Transmission - Manual</b>	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate15571-58-1
	Lead7439-92-1

<b>Underbody Shields and Wheel Liners</b>	Lead7439-92-1
<b>Window Regulator</b>	Boric acid10043-35-3
	Lead7439-92-1
<b>Wiper Assembly (Rear, Front) &amp; Washer System</b>	Lead7439-92-1